

### **AMENDMENTS TO THE DRAWINGS**

The attached "Replacement Sheets" of drawings include changes to Figs. 5, 6, and 7, and a new Fig. 5a. Additionally, the attached "Replacement Sheets" include changes to all of the figures to replace handwritten element numbers and leader lines with computer generated element numbers and leader lines. The attached "Replacement Sheets," which include Figs. 1 through 10b, replace the original sheets, including Figs. 1 through 10b.

Applicants have submitted a new drawing figure, namely Fig. 5a, to illustrate a locking ring engaging a first threaded portion of a housing. Support for Fig. 5a can be found in at least paragraphs [0036] and [0038]. Therefore, no new matter is being submitted with the new drawing figure. Additionally, Fig. 5 has been changed to Fig. 5b to remain consistent with the detailed description.

A replacement drawing for Fig. 6 has also been submitted to correct the leader line for element 28a. Element 28a was inadvertently leading to the wrong element on the original drawing figure.

Applicants have also submitted a replacement drawing for Fig. 7 such that the thread protrusion 28a is scaled proportionally to be consistent with the thread protrusion 28a in Figure 8a.

Attachment: Replacement Sheets





FIG. 1



REPLACEMENT SHEET(S)

2/10




FIG. 2



REPLACEMENT SHEET(S)




FIG. 3a




FIG. 3b



REPLACEMENT SHEET(S)

4/10




FIG. 4



REPLACEMENT SHEET(S)

5/10




FIG 5a




FIG. 5b



REPLACEMENT SHEET(S)

6/10




FIG. 6



REPLACEMENT SHEET(S)

7/10




FIG. 7




FIG. 8a






FIG. 8b




FIG. 8c

REPLACEMENT SHEET(S)



9/10




FIG. 9



REPLACEMENT SHEET(S)

10/10




FIG. 10a




FIG. 10b